



Service Bulletin

PRELIMINARY INFORMATION

Subject: 1.4L (RPO LV7) Engine Exchange Program

Models: 2016 Chevrolet Spark
equipped with 1.4L (RPO LV7)

This PI was superseded to update Engine Exchange Program has ended. Please discard PIP5359.

This engine can now be ordered through the regular GM CCA parts process or PQC process for required dealers.

GM Engineering would like to thank all dealers that participated in this parts restriction.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION