

**On-car analysis list from June 30th, 2016
please contact VW Helpline before attempting repair**

	Models	MY	Engine	Transmission	Topic	Customer Complaint
Powertrain	Jetta Hybrid	13 - 15	All	All	MIL-on P309F and P309D Fault Code	MIL-on no electric drive mode, untouched vehicles
	Tiguan	15	All	All	Rear O2 Sensor Fault	MIL-on fault P013E in the ECM
	Passat, Jetta, Golf Sportwagen, Beetle, Beetle Conv	15	2.0TDI (CVCA, CRUA)	All	MIL-on P164B	Customer states MIL on, P164B in ECM (untouched vehicles, Engine production before January 2015 or after March 2015 only)
	All	13-15	2.0T (CCTA, CBFA)	All	MIL-on P0011 P0016	MIL-on with fault code P0011 and or P0016 in the ECM (untouched vehicles)
	Passat	16	1.8T (CPRA, CPKA)	All	MIL-on P0299	MIL-on with loose boost hose(s) (untouched vehicles)
	Golf R	16	All	All	Turbo Failure	Customer states noise form the engine/turbo
	Golf/GTI, Golf Sportwagen	15-16	All	All	Fuel Level Sensor	Fuel gauge not reading full after topping up the fuel (untouched vehicles)
	Golf/GTI, Golf Sportwagen	16	All	All	Fuel Line Noise	Fuel line rattle from below the vehicle (untouched vehicles after VIN GM016333)
	GTI, Tiguan, CC	13-15	2.0T (CCTA, CBFA)	All	MIL-on P2015	MIL-on with fault code P2015 in the ECM (Only vehicles with 10k miles or more)
Chassis	GTI	16	All	Standard	Clutch Pedal Noise	Clutch pedal squeal/squeak when operating clutch pedal
Body	Jetta	16	All	All	Sunroof Pinch Protection	Sunroof does not close, bounces back open (untouched vehicles)