

6/22/16

MY 13, 14, 15 D2, DD, DJ, DP

## **GPOP - Issue Review System**

**Part Number:** 68206041A\$

**Part Description:** Fan Support Assembly, Fan Support Bearing, Fan Pulley

**Issue Description:** If you are replacing this part due to fan hub bearing failure, please also replace the fan clutch assembly using current Mopar stock (part number 52014729A\$).~  
Once installed, contact Christine Donegan at (866) 799-1692 ext 1257 to initiate a fast track request for the return of the parts for analysis.~

~  
Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquires. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.