

6/22/16

MY 16 All Models

GPOP - Issue Review System

Part Number: 68066351A\$, 56046760A\$, 56046681A\$, 05035395A\$, 05026679A\$, 68227842A\$, 68216173A\$, 68232719A\$, 68234957A\$, 68234958A\$, 68234959A\$, 68234960A\$, 68243451A\$, 68243452A\$, 68243454A\$, 56046774A\$, 68060750A\$, 68143505A\$, 68143500A\$, 68143504A\$, 68143502A\$, 68143506A\$, 68143501A\$, 68143507A\$, 68143503A\$, 68223736A\$, 68223737A\$, 68223738A\$, 68223739A\$, 68240167A\$, 68240168A\$, 68240169A\$, 68150061A\$, 68066349A\$, 56046759A\$, 56046758A\$, 68051387A\$, 68066350A\$, 68225803A\$, 68225802A\$

Part Description: Keyfob

Issue Description: 2016 Vehicle Keyfobs with Passive Entry Keyless Go Feature - Engineering is investigating a keyfob unable to program or no function or low keyfob coin battery condition.~

Prior to replacing keyfob on MY16 vehicles, please contact Raja Charabuddi on cell (248) 202-7313. If no response within 15 minutes, proceed with repair.~

~
Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
