

6/29/2016 MY14, 15 KL MY15 UF

## **GPOP - Issue Review System**

**Part Number:** 68227808A\$, 68090615A\$, 68090612A\$, 52123642A\$

**Part Description:** Rear Differential or Rear Differential Actuation Motor

**Issue Description:** If you are attempting to repair a whistling/high pitched noise from the rear differential area FCA has released TSB 03-003-16 June 21 to address this concern

~ ~  
Contact Us at [CAGRIS@Chrysler.com](mailto:CAGRIS@Chrysler.com) for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquires. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.