

TO: Hyundai Dealership General Managers, Sales Managers,
Service Managers, Parts Managers, and Warranty
Administrators
FROM: Hyundai Motor America
DATE: September 20, 2016
SUBJECT: Recall 146 - 2013 Elantra (MD/UD) Brake Pedal Stopper
Replacement (TSB# 16-01-039)

Hyundai Motor America is conducting Recall 146 to replace the Brake Pedal Stopper on certain 2013 Model Year Elantra vehicles. Recall 146 provides a procedure to replace the Brake Pedal Stopper.

In order to identify only those vehicles affected by Recall 146, it will be necessary to access Hyundai Motor America's "Warranty Vehicle Information" screen via WEBDCS before starting the repair. The "Warranty Vehicle Information" screen will identify affected vehicles with an open Recall 146.

A listing of VEHICLES is also located on WEBDCS, SERVICE tab, select INFORMATION, and select UNCOMPLETED CAMPAIGN VIN LISTING - Retailed.

TSB #16-01-039 is available on Hyundai's Website as of September 20, 2016. It contains instructions on performing the service and submitting the campaign claim.

An initial shipment of Brake Pedal Stoppers began shipping on September 20, 2016 to all dealers.

It is IMPORTANT TO SUBMIT A CAMPAIGN CLAIM FOR EACH VEHICLE SERVICED so your dealership can be compensated for your work and Hyundai can maintain accurate records of campaign completions.

LEGAL LIABILITY NOTICE: You are required to keep confidential any and all information and documents provided to you by Hyundai Motor America in the conduct of carrying out work for this recall. Hyundai Motor America dealers may use owner information provided for the campaign only for the purpose of conducting and performing this service campaign, and for no other purpose.

Hyundai appreciates your cooperation and support. Questions may be directed to your District Parts and Service Manager or Warranty HELPREP line at 1-877-446-2922.

HYUNDAI MOTOR AMERICA