

June 2016

Dear 2015 TLX V6 owner:

The warranty book that was provided on the owner's CD in the glove box of your vehicle was missing information. Specifically, the hydraulic control unit was not included in the Emission Warranty Parts List located on the last page. To remedy this error, enclosed is a new owner's information CD with the corrected information. Please replace your original CD with this new one.

If you would like to view this warranty book or any other owner information concerning your vehicle online, please visit the Acura Owners website at **owners.acura.com** for the most current information.

We apologize for any inconvenience this may have caused you.

Sincerely,

American Honda Motor Co., Inc.
Acura Automobile Division

