

Always Fill Replacement CVT to Proper Fluid Level

AFFECTED VEHICLES

2013–16 Accord L4 with CVT, 2015–16 CR-V

Replacing a CVT? Make sure you fill the replacement CVT to the proper fluid level with Honda Genuine HCF-2. If you don't, you could wind up with transmission failure and a comeback. A CVT with low fluid will make pump noise when the vehicle accelerates.

Since the service information doesn't include fill amounts for a replacement CVT, refer to this chart for those amounts:

Model/Year	Fill Amount - Liters	Fill Amount - Quarts
2013–16 Accord L4 with CVT	5.0	5.3
2015–16 CR-V (2WD)	5.0	5.3
2015–16 CR-V (4WD)	5.7	6.0