

[Next Unread Message](#)[View Message](#)

<b>Sent on</b>	10	04	2016	<b>Expires on</b>	01	01	2017
----------------	----	----	------	-------------------	----	----	------

<b>From</b>	Campaign Administration
-------------	-------------------------

<b>Subject</b>	Product Update: 2016 Odyssey Primer Not Applied to Sliding Door Spot Welds
----------------	--

DATE: October 4, 2016

TO: All Honda Sales, Service &amp; Parts Managers and Personnel

FROM: Campaign Administration

Re: Product Update: 2016 Odyssey Primer Not Applied to Sliding Door Spot Welds

Today, October 4, 2016, American Honda Motor, Co., Inc. is announcing a product update for 110 model year 2016 Honda Odyssey vehicles to prevent or correct possible rust and corrosion from the left sliding passenger door in the affected area. Any affected vehicles in dealer stock should be fixed prior to selling.

**Basic Problem**

During manufacturing, three spot welds inside the top of the driver's side sliding door were not properly finished with primer. The untreated metal is susceptible to corrosion.

**The Repair**

The top of the left side passenger door will be fixed on the inside of the window channel. To minimize the possibility of rust or corrosion, the area must be repaired of any current corrosion, cleaned and primer applied to the metal surfaces affected.

**Service Bulletin**

Service bulletin 16-079, *Product Update: Primer Not Applied to Sliding Door Spot Welds* has been posted to the Service Information System today in support of this proactive campaign. It includes material, warranty and repair procedure information related to this product update.

**Parts and Materials Information**

There are no orderable parts related to this repair. The factory (Honda Manufacturing Alabama) will be sending repair kits to dealers with affected vehicles based on appointments set by AHM customer service. Please do not attempt to place orders for these kits through your Parts Department.

**Warranty**

Warranty information is detailed in S/B 16-079, *Product Update: Primer Not Applied to Sliding Door Spot Welds*.

As always, please make sure to check iN VIN Status to determine if a particular vehicle is eligible for these or any other campaigns.

Click [here](#) for a copy of 16-079.