
2014-2016 RDX Leak from Fuel Pump Connection

Background

American Honda (AHM) is investigating certain 2014-2016 RDXs with evidence of fuel leak from the fuel tank to the fuel pump connection. To fully understand the cause of this condition, AHM would like to collect specific parts from the vehicle prior to you attempting a repair of any kind.

Qualifiers

AHM is interested **ONLY** if the vehicle meets the following requirements:

1. Must confirm fuel leak from the fuel tank to the fuel pump connection.
2. No previous repair relating to the fuel tank or the fuel pump.

Action Required

If you have or know of such a vehicle, please call Technical Research & Support (TRS) Group at 800-880-1072. TRS will need to record certain vehicle information and provide you with further instructions.

Thank you.