

[Next Unread Message](#)**View Message**

Sent on	02	03	2016	Expires on	02	17	2016
From	Parts and Service Division						
Subject	Request for Parts: 2014-2016 RDX Leak from Fuel Pump Connection						

PRIORITY/ACTION REQUIRED

To: All Acura Service Managers/Consultants
From: Technical Research & Support Group
RE: Request for Parts: 2014-2016 RDX Leak from Fuel Pump Connection

This message is solely directed to Acura dealership personnel; please handle accordingly.
Print this *iN* message and provide a copy to the Shop Foreman and all Service Consultants.

Background

American Honda (AHM) is investigating certain 2014-2016 RDXs with evidence of fuel leak from the fuel tank to the fuel pump connection. To fully understand the cause of this condition, AHM would like to collect specific parts from the vehicle prior to you attempting a repair of any kind.

Qualifiers

AHM is interested ONLY if the vehicle meets the following requirements:

1. Must confirm fuel leak from the fuel tank to the fuel pump connection.
2. No previous repair relating to the fuel tank or the fuel pump.

Action Required

If you have or know of such a vehicle, please call Technical Research & Support (TRS) Group at 800-880-1072. TRS will need to record certain vehicle information and provide you with further instructions.

Thank you.