

SSM 45888	Some 2015-2016 F150 vehicles may exhibit an exterior door handle that does not release the door latch and/or a power door lock that is not unlocking with key fob or the interior unlock button. If any of these concerns are present and normal workshop manual diagnosis leads to a handle, latch, or cable replacement, be sure to inspect the exterior handle cable for correct routing and attachment prior to replacing any components. A properly routed cable should sit in the rearward pocket of door handle near the part tag. The cable arrow-head retainer clip should be fully seated and locked into the exterior handle bracket.
--------------	--