

SERVICE ADVISORY # 16-265

Summerland Mini Fuse

It has been determined the below listed vehicles were manufactured with an undersized 15 amp fuse placed in the battery charging circuit which should have a 30 amp fuse. The circuit is wired and rated for 30 amp capacity. This advisory explains how to correct.

Model and Serial Numbers Included: 2017 Summerland Mini
1700FQ, 1750RD, 1800BH, 1850FL

Serial Number Range: H3150644 – H3151103

Parts Required per Unit: (1) 30 Amp Blade Fuse - Acquire locally

Tools Required: - Ink Pen

ONE INSPECTION and REPAIR

Step 1 Locate the trailer on a level, flat and hard surface. Chock the wheels.

Step 2 Locate the fuse panel in the unit. Remove the 15 amp fuse from the number 6 location of the fuse panel. Replace the fuse with a 30 amp fuse. Change the noted fuse size of position 6 on the information label from 15 to 30.



Fig. 1



Fig. 2

TWO WARRANTY REIMBURSEMENT

Submit the request on Key Express using **Flat Rate Code # 7126542B** with **Service Advisory #16-265** noted in the customer complaint section. The time authorized for this repair is **.2 hours**.

If you have any questions, please call Customer Service at **(866) 273 - 1452**