


Dual Exhaust Tips Look Uneven?

AFFECTED VEHICLES

2017 Accord V6 and 2017 Accord Sport

Do those dual exhaust tips look a bit uneven? Chances are one of the rubber exhaust hangers isn't properly installed.

The rubber exhaust hanger is directional and must be installed with the word **UP** in its center, facing up. If it's not, the muffler won't hang like it should and the attached exhaust tip will look uneven with the other one.



To address this issue, make sure both rubber exhaust hangers are properly installed.