

View Message

Sent on 04 01 2016 Expires on 04 22 2016

From Motorcycle National Field Service

Subject STOP SALE NOTICE: 2016 SXS1000 (Pioneer 1000)

Re: STOP SALE NOTICE

Dear Honda Dealer:

Honda is announcing an STOP SALE on model year 2016 SXS1000 (Pioneer 1000) vehicles to repair a potentially defective front door striker on affected vehicles. If a front door striker breaks, the door could open unexpectedly.

Effective immediately, YOU MUST NOT SELL any NEW or USED 2016 SXS1000 within the following VIN ranges:

AFFECTED UNITS

Model	Area Code	VIN Range	
SXS1000M3	A	1HFVE048*G4000665 thru	1HFVE048*G4000964
SXS1000M3	AC	1HFVE04L*G4000121 thru	1HFVE04L*G4000180
SXS1000M3P	A	1HFVE04A*G4002444 thru	1HFVE04A*G4003603
SXS1000M3P	2AC	1HFVE04N*G4000181 thru	1HFVE04N*G4000240
SXS1000M5P	A	1HFVE040*G4001087 thru	1HFVE040*G4001806
SXS1000M5P	AC	1HFVE04H*G4000181 thru	1HFVE04H*G4000300
SXS1000M5D	A	1HFVE042*G4003488 thru	1HFVE042*G4004087
SXS1000M5D	2A	1HFVE046*G4000723 thru	1HFVE046*G4000782
SXS1000M5D	3A	1HFVE04P*G4000063 thru	1HFVE04P*G4000242
SXS1000M5D	3AC	1HFVE04R*G4000061 thru	1HFVE04R*G4000120

* Denotes check digit

SERVICE BULLETIN

Service Bulletin SXS1000 #1, which includes the affected VIN range, repair procedure, parts information, as well as warranty claim information, is forthcoming.

Make sure all departments in your dealership are aware of this action.

If you have any questions, please contact AHM TechLine through TechLine Connect on *iN* or contact your District Service Manager.

Sincerely,
American Honda Motor Co., Inc.

Bradley Little
Manager, National Field Service
Motorcycle Division

Bulletin #: 16-0103