



2016 CC

Engine	Part	Part Number	Quantity
2.0L Turbo: CCTA, CBFA	Oil Filter	06J115403Q	1
	VW 502 00 Use synthetic oil SAE 5W-40, SAE 5W-30	N/A	4.7L (4.9qt)
	Drain Plug Gasket	N 0138157	1
	Pollen Filter (20K Only)	1K1819653B	1
	Air Filter	1K0129620D	1
	Wiper Blade Set	3C8998002	1
Miscellaneous		1	
	Battery (Amp. Req. Vary)	000915105*	1
	Battery (Amp. Req. Vary)	000915105*	1

Engine	Part	Part Number	Quantity
3.6L VR6: CNNA	Oil Filter	03H115562	1
	VW 502 00 Use synthetic oil SAE 5W-40, SAE 5W-30	N/A	5.5L (5.8qt)
	Drain Plug W/Gasket	N 90813202	1
	Pollen Filter (20K Only)	1K0819644B	1
Miscellaneous	Air Filter	1K0129620	1
	Wiper Blade Set	3C8998002	1
	Battery (Amp. Req. Vary)	000915105*	1
	Battery (Amp. Req. Vary)	000915105*	1
	Battery (Amp. Req. Vary)	000915105*	1

***VIN Required**

2016 CC Service Reminder Reset

Resetting the oil change service reminder

If the service was not performed by an authorized Volkswagen dealer or an authorized Volkswagen Service Facility, the oil change service reminder can be reset as follows:

- 1. Switch off the ignition.
- 2. Press and hold the **0.0/SET** button in the instrument cluster.
- 3. Switch on the ignition.
- 4. Release the 0.0/SET button.
- 5. A confirmation message appears in the display. Confirm request with **OK** button on the multi-function steering wheel.

Resetting the inspection service reminder

If the service was not performed by an authorized Volkswagen dealer or an authorized Volkswagen Service Facility, the inspection service reminder can be reset as follows:

- 1. Switch off the ignition.
- 2. Switch on the emergency flashers.
- 3. Press and hold the **0.0/SET** button in the instrument cluster.
- 4. Switch on the ignition.
- 5. Release the 0.0/SET button.
- 6. A confirmation message appears in the display. Confirm request with the **OK** button on the multi-function steering wheel.
- 7. Switch off the emergency flashers.

Do **not** reset the service reminder between service intervals; otherwise incorrect information will be displayed.

The service reminder disappears after a few seconds or after the OK button on the multi-function steering wheel has been pushed.

For current fluid capacity charts, they can be found on ServiceNet under the Maintenance tab.