



# 2016 Passat

Engine	Part	Part Number	Quantity
1.8L Turbo: CPKA, CPRA	Oil Filter	06K115408	1
	VW 502 00 Use synthetic oil SAE 5W-40, SAE 5W-30	N/A	5.5L (5.7qt)
	Drain Plug W/Gasket	N 91167901	1
	Air Filter	5C0129620	1

Engine	Part	Part Number	Quantity
3.6L VR6: CDVB	Oil Filter	03H115562	1
	VW 502 00 Use synthetic oil SAE 5W-40, SAE 5W-30	N/A	5.5L (5.8qt)
	Drain Plug W/Gasket	N 908132	1
	Air Filter	1K0129620B	1

Miscellaneous	Part	Part Number	Quantity
Miscellaneous	Pollen Filter (PR-KH6)	1K819644B	1
	Pollen Filter (PR-9AK)	1K1819653B	1
	Wiper Blade – Left >> D – 01.08.2016	561955425	1
	Wiper Blade – Right >> D – 01.08.2016	561955426	1
	Battery (Amp. Req. Vary)	000915105*	1
	Battery (Amp. Req. Vary)	000915105*	1
	Battery (Amp. Req. Vary)	000915105*	1

#### **\*VIN Required**

© 2016 Volkswagen Group of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

# 2016 Passat Service Reminder Reset

#### Resetting the oil change service reminder

If the service was not performed by an authorized Volkswagen dealer or an authorized Volkswagen Service Facility, the oil change service reminder can be reset as follows:

### Vehicles with Premium display:

- 1. Switch off the ignition.
- 2. Press and hold the **0.0/SET** button in the instrument cluster.
- 3. Switch on the ignition.
- 4. Release the 0.0/SET button.
- 5. A confirmation message appears in the display. Confirm request with the **OK/RESET** in the windshield wiper lever or the **OK** button on the multi-function steering wheel.

### Vehicles with Basic display:

- 1. Switch off the ignition.
- 2. Push the **0.0/SET** button in the instrument cluster and hold down.
- 3. Switch on the ignition.
- Release the 0.0/SET button and push the E/ ④ button in the instrument cluster within about 20 seconds.

# Resetting the inspection service reminder

If the service was not performed by an authorized Volkswagen dealer or an authorized Volkswagen Service Facility, the inspection service reminder can be reset as follows:

#### Vehicles with Premium display:

- 1. Switch off the ignition.
- 2. Switch on the emergency flashers.
- 3. Press and hold the **0.0/SET** button in the instrument cluster.
- 4. Switch on the ignition.

© 2016 Volkswagen Group of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

# Vehicles with Premium display:

- 5. Release the 0.0/SET button.
- A confirmation message appears in the display. Confirm request with the <u>OK/RESET</u> in the windshield wiper lever or the <u>OK</u> button on the multi-function steering wheel.
- 7. Switch off the emergency flashers.

#### Vehicles with Basic display:

- 1. Switch off the ignition.
- 2. Switch on the emergency flashers.
- 3. Push the **0.0/SET** button in the instrument cluster and hold down.
- 4. Switch on the ignition.
- Release the 0.0/SET button and push the ⊡/④ button in the instrument cluster within about 20 seconds.
- 6. Switch off the emergency flashers.

**b** Do **not** reset the service reminder between service intervals; otherwise incorrect information will be displayed.

The service reminder disappears after a few seconds or after the **OK/RESET** button on the windshield wiper lever or the **OK** button on the multi-function steering wheel has been pushed.

For current fluid capacity charts, they can be found on ServiceNet under the Maintenance tab.