



# Tech Tips

---

**TT 87-16-02**

**Date: July 29, 2016**

**2013 – 2016 Passat, Jetta, 2015-2016 Golf, GTI, Sportwagen,  
Golf R – Weak or No Air Flow from Vents – Evaporator  
Freezing**

---

If the customer complains of air flow sporadically dropping off or becoming weak while driving, check the following when the concern is present:

If the condition is confirmed to be from the evaporator freezing, connect AC gauges to monitor the AC pressure. If AC is ON, switch to the OFF position. Make sure defrost mode is OFF as well.

If the gauges still show compressor operation, disconnect the N280 to see if the compressor shuts OFF. If the compressor still shows operation after disconnecting the N280, replace the compressor and perform the AC flush per technical bulletin 2019947 (V871516). If the condition is not caused from evaporator freezing, further diagnosis will be required to check operation of the blower motor and HVAC flap motors.