



Tech Tips

TT 90-12-04

Date: August 31, 2012

2010-2016 CC, Eos, Golf, GTI, Sportwagen, Tiguan, 2012-2016
Passat, Beetle, Beetle Convertible - Service Interval Settings
after Instrument Cluster Replacement

August 5, 2016: Update to Year Applicability.

After instrument cluster replacement, service interval maximum values may need to be manually set. To set values manually, use ODIS Control module OBD to select 17- Instrument Cluster, then adaptation. Channel "SIA: maximum value of distance to service" should be set to 16100 km and channel "SIA: maximum value of time to service" should be set to 372 days.

Adaptation/parameter	Current value	Entry	Unit
☐ Cruise control display			
☐ Units adjusted			
☐ WIV: minimum value of time between inspections			
☐ SIA: maximum value of distance to service	16,100		km
☐ SIA: maximum value of time to service	372		d
☐ Staging			
☐ Indicator light for start-stop operation			