

8/3/2016

MY15, 16

JK

GPOP - Issue Review System

Part Number: 68089579A\$

Part Description: Console Lid

Issue Description: JK ONLY - If you are replacing the console lid because it does not open properly or because it does not close properly, please also replace the console base and the lock cylinder (04746315) in addition to the console lid. If you have any questions, please call Mike Wicker on cell (248) 821-9350 prior to replacing the component. If you don't receive a response within 15 minutes, please continue with normal repair procedure.~

~_____~
Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquiries. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
