



SERVICE BULLETIN

| | | |
|-----------------------------|-------------------------|--------------------------|
| Classification: EL15-040 | Reference: NTB16-094 | Date: October 5, 2016 |
|-----------------------------|-------------------------|--------------------------|

2013 – 2015 PATHFINDER; DOOR MIRROR GLASS WILL NOT RETURN AFTER SHIFTING REVERSE TO DRIVE

APPLIED VEHICLES: 2013 – 2015 Pathfinder (R52) equipped with ADP
2014 Pathfinder Hybrid (R52), equipped with ADP

APPLIED VIN: 2013 – 2014, all VIN's
2015, built before 5N1AR2M(**)FC 661844

APPLIED DATE: Built before April 7, 2015


IF YOU CONFIRM

The door mirror glass (LH and RH) automatic tilt down-up feature does not return the glass to original position after shifting from reverse to drive.

ACTION

Replace the Automatic Drive Positioner (ADP) Control Unit.

- Use the new part listed in the Parts Information.
- Refer to the Electronic Service Manual (ESM), section ADP-Automatic Drive Positioner, for replacement information.



Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.

PARTS INFORMATION

| DESCRIPTION | PART NUMBER | QUANTITY |
|--|--------------------|-----------------|
| CONTROLLER ASSEMBLY-POWER SEAT (ADP Control Unit) | 28565 – 3JA1A | 1 |

CLAIMS INFORMATION

Submit a Primary Part (PP) type claim using the following claims coding:

| DESCRIPTION | PFP | OP CODE | SYM | DIA | FRT |
|--------------------------|---------------|----------------|------------|------------|------------|
| Replace ADP Control Unit | 28565 – 3JA1A | VH72AA | HD | 32 | (1) |

(1) Reference the current Nissan Warranty Flat Rate Manual and use the indicated FRT.

