



Service Bulletin

PRELIMINARY INFORMATION

Subject: Upfitter Configurable Auxiliary Circuits (Police And Special Service Vehicles)

Models: 2015-2017 Chevrolet Tahoe
With Police Package (RPO 9C1) or Special Service Vehicle (RPO 5W4)

This PI was superseded to add the 2016/2017 models. Please discard PIT5325.

Condition/Concern

Starting with the new 2015 -2017 Tahoe Police Patrol Vehicle (PPV) / Special Service Vehicle (SSV), four relay controlled circuits can be utilized when installing special first responder equipment. These circuits are bundled together and located at or near the center console area

Please reference the latest version of GM Upfitter Integration Bulletin 118 for additional information on these circuits. It can be found at <http://www.gmupfitter.com/>, under the "Technical Bulletin" Tab and then "Show all bulletins."

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION