



Service Bulletin

INFORMATION

Subject: Information on Stop/Start AutoStop Active During Low Speed Maneuvers and While Parking Vehicle

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Cadillac	ATS	2016	2017				
	CTS						

Involved Region or Country	North America and N.A. Export Regions
Additional RPOs	KL9
Condition	Some customers may comment that the AutoStop is active and interferes with low speed maneuvers and while parking the vehicle

Information

This is a normal condition and no repairs should be made.

If the customer finds the AutoStop objectionable during low speed or while parking, advise the customer the system can be disabled using the disable button. This should be done before attempting the low speed maneuvers or parking the vehicle.

Version	1
Modified	

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION