



Service Bulletin

TECHNICAL

Subject: Information on Servicing Black Button Passive Entry Passive Start (PEPS) Button Door Handles

Attention: This PI also applies to any of the above models that may be Export vehicles.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Camaro	2016	2016	SOP	September 9, 2015	All	All

Some 2016 Chevrolet Camaros were produced with outside door handles that are equipped with black PEPS buttons.

The door handle black PEPS button is not available for service.

If a customer needs one of the handles serviced, all the handles will need to be replaced with chrome PEPS button handles.

Parts Information

Description	Part Number	Qty
HANDLE KIT- FRT S/D O/S	13511252	2

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
2080618*	Front Door Handles Replacement	1.2 hrs

*This is a unique Labor Operation for Bulletin use only.

Version	1
Modified	

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools,

safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION