



# Service Bulletin

## PRELIMINARY INFORMATION

**Subject:** PQC Part Restriction - 2015 Camaro Commemorative Edition Fender Badge Restriction Has Ended

**Models:** 2015 Chevrolet Camaro equipped with RPO B6Z

*This PI was superseded to update Part Restriction. Please discard PIC6094.*

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

### Condition/Concern

The emblem / badge shown below for the Commemorative Edition 2015 Camaro had previously been on parts restriction. As of 3/28/16, this part restriction has ended and dealership personnel can now order this part as needed through CCA parts.



Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION