


HFL Microphone Concern? *Don't* Replace the Front Individual Map Light Assembly

AFFECTED VEHICLES

2015-16 CR-V (EX and above)

EDITOR'S NOTE: This article revises the one posted in **July 2015**. Changes are highlighted in **yellow**.

On 2015-16 CR-Vs (EX and above), the *Bluetooth*® HandsFreeLink® (HFL) and HFL microphone are built into the audio unit/audio-navigation unit. There's no longer a separate HFL control unit in the shift lever panel or HFL microphone in the front individual map light assembly.



Keep this in mind if you're troubleshooting HFL for a microphone concern. Replacing the front individual map light assembly **won't** fix anything since there's no microphone in this part!