



# Technical Service Bulletin

---

## 01 MIL on (DTC P240F) EGR Slow Response stored in ECM

01 16 91 2045998/1 December 1, 2016.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A6	2014 & 2016	All	3.0 V6 TDI diesel
A7	2014 & 2016	All	3.0 V6 TDI diesel
A8	2014 - 2015	All	3.0 V6 TDI diesel
Q5	2014 - 2015	All	3.0 V6 TDI diesel

## Condition

- MIL on.
- **DTC P240F00** (Exhaust Gas Recirculation Slow Response) is stored in the engine control module (ECM), J623 (address word 0001).

## Technical Background

EGR calibration improved to avoid slow response fault during high load/low rpm conditions.

## Production Solution

EGR calibration optimized.

## Service

### SVM Update Instructions

1. Follow all instructions in TSB 2011732: *00 Software Version Management (SVM), operating instructions*.
2. Update the engine control module (ECM), J623 (address word 0001), using the SVM action code as listed in the table below if necessary:



# Technical Service Bulletin

Model	Engine	Old Software Part Number	Old Software Version	New Software Part Number	New Software Version (or higher)	SVM Code Input
Q5	CPNB	8K5907401J	< 0005	8K5907401J	0005	01A209
Q5	CPNB	8K5907401S	*	8K5907401AC	0002	01A209
A6,A7	CPNB	4G0907401N	< 0005	4G0907401N	0005	01A209
A6,A7	CPNB	4G0907401T	*	4G0907401AA	0002	01A209
A8	CPNA	4H0907401F	< 0009	4H0907401F	0009	01A209
A8	CPNB	4H0907401K	*	4H0907401N	0002	01A209

## Warranty

<b>Claim Type:</b>	<ul style="list-style-type: none"> <li>• 110 up to 48 Months/50,000 Miles.</li> <li>• G10 for CPO Covered Vehicles – Verify Owner.</li> <li>• If vehicle is outside any warranty, this Technical Service Bulletin is informational only.</li> </ul>		
<b>Service Number:</b>	2360		
<b>Damage Code:</b>	0039		
	<b>For all vehicles:</b>		
	Software update	2360 2599	50 TU
<b>Diagnostic Time:</b>	GFF	0150 0000	20 TU
	Road test prior to service procedure	No allowance	0 TU
	Road test after service procedure	No allowance	0 TU



# Technical Service Bulletin

---

	Technical diagnosis at dealer's discretion (Refer to Section 2.2.1.2 and Audi Warranty Online for DADP allowance details)
<b>Claim Comment:</b>	As per TSB #2045998/1

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

## Additional Information

All parts and service references provided in this TSB (2045998) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.

©2016 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.