

2/3/16 MY14,15

KL

MY15 UF

GPOP - Issue Review System

Part Number: 68227808A\$, 68090615A\$, 68090612A\$, 52123642A\$

Part Description: Rear Differential or Rear Differential Actuation Motor

Issue Description: If you are attempting to repair a whistling/high pitched noise from the rear differential area FCA is currently working on a fix for the concern. Please do not replace the differential motor or the rear differential module for this concern. A field fix will be available early the second quarter of 2016.

~
Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquires. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.