GPOP - Issue Review System

Part Number: 68018109A\$, 68223051A\$, 68089742A\$

Part Description: Actuator- A/C Heater

Issue Before replacing this actuator call Matt Sasina at cell (248) 464-4982. If no response

Description: in 15 minutes, continue with repair.

Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquires. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.