

7/6/2016

MY15 UF, KL

GPOP - Issue Review System

Part Number: 68225064A\$

Part Description: SENSOR-WASHER FLUID LEVEL

Issue Description: Please call Chuck Hood cell (248) 613-7591 to describe issue. Prior to replacing this part due to "Low Washer Fluid" message on the dash when the washer fluid bottle is full, please verify I101 48-way black connector regarding W11 & W1 circuits, then clean and secure as needed to complete. If diagnostics point to Float Sensor failure and requires replacement, carefully remove SENSOR-WASHER FLUID LEVEL so as to not damage part for FCA analysis. If no response in 15 minutes continue with repair.

~

—

Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquires. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.

—