

7/13/2016 MY17 RU

GPOP - Issue Review System

Part Number: 68322289A\$, 68322290A\$, 68227756A\$, 68322311A\$, 68225206A\$

Part Description: A/C Suction/Liquid Line, A/C Discharge Dine, A/C Compressor

Issue Description: For RU bodies ONLY; Issues with leaks in the above A/C components. Also issues with compressor performance. Before replacing any of the components listed above call Michael Romm at cell (248) 766-5465. If no response in 15 minutes, please proceed with repair.

Be prepared to answer the following questions:

- Is A/C functional or not?
- If not, does HVAC have the latest software per TSB 24-006-16 ?
- Is compressor clutch engaging? If not, then using wiTECH, was A/C request active when clutch was not engaging?
- Is there any evidence of refrigerant leaks / dye anywhere in the A/C system?
- If the refrigerant has been reclaimed, what was the amount?

~_____
Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquires. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
