

July 20, 2016 MY 15, 16 KL, PF, UF

GPOP - Issue Review System

Part Number: 68103198A\$, 68103197A\$, 68193950A\$

Part Description: A/C Compressor

Issue Description: This applies to 2015 and 2016 KL, UF and PF. Before replacing the AC compressor for noise, leaks , or for an inop condition:~

After these questions have been answered please call one of the individuals below.~

- 1) Check all AC plumbing connection for leaks with UV light. Any leaks found?~
- 2) Does compressor pulley and clutch hub turn freely, or are they seized?~
- 3) What was the amount of the recovered refrigerant?~

After these questions have been answered please call one of the individuals below:~

Stev at cell (248) 867-0061~

Mark Briolat at cell (248) 345-0127~

If no response in 15 minutes, please continue with repair.~

If the compressor is replaced, then:~

- 4) Drain oil from compressor. What was quantity of oil recovered?

~ _____ ~

Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquires. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
