

9003641 10/30/2016 MY15, 16, 17 VM

GPOP - Issue Review System

Part Number: 68261744A\$

Part Description: Shaft, Axle Half

Issue Clunking noise at low speed due to worn Half Shaft, CV Joint or Tripod Joint.

Description: Prior to any work or replacement of the part, please contact: Mike Perion @ cell: (248) 420-9016. If you don't receive a call back within 15 minutes, please proceed with normal repair.

~_____
Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.