

9003649 10/30/2016 MY17 RU

## GPOP - Issue Review System

**Part Number:** 05106254A\$, 05106253A\$, 68194149A\$

**Part Description:** Halfshaft

**Issue Description:** When replacing this component it is required that the hub nut; 06509298AA, be replaced at the same time. Ensure the hub nut is torqued to the service manual specifications for this vehicle. The torque specification for the hub nut is 163 N.m or 120 Ft.Lbs.~

~  
Contact us at [CAGRIS@Chrysler.com](mailto:CAGRIS@Chrysler.com) for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.  
~