

1/26/16

MY2000 GS, NS

MY2004 WG, WJ

GPOP - Issue Review System

Part Number: 05191925A\$, 52079428A\$, 52079883A\$

Part Description: Radiator

Issue Description: If vehicle comes in for transmission fluid leaking from trans-oil cooler fittings on the radiator, please check the following before replacing the radiator/cooler:~

1. Remove both of the transmission lines from the cooler's top/bottom flared fittings on the radiator. ~
2. Loosen the hex nut on the top flared fitting on the radiator tank.~
3. Torque the top flared fitting to 235 +/- 15 Lb-In.~
4. Torque hex nut to 100 +/- 10 Lb-In.~
5. Repeat for bottom flared fitting.~
6. Reinstall transmission line per normal installation procedures and ensure correct fluid level.~

~

If vehicle is in need of a new radiator for another reason, check the new radiator for correct torque on the trans-oil cooler fitting per steps 2-5 above.~

~

If radiator has a yellow mark by the trans-oil cooler fittings the torque does not have to be checked.

~

~
Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquires. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
