

TECHNICAL SERVICE BULLETIN

TSB#: 16-035

Job Code: 9802323

Flat Rate: 1.3 hr

Date of Publication

December 2016

NOTE: This Technical Service Bulletin will be valid within (1) year from the original date of publication.

Action Required

Inspect sealant around all items mounted on roof and replace when **cracks** are visible.

Affected Units

2017 Solstice Fifth Wheels	H2	HA5051-5060	HD5051-5053
		HB5053-5068	HE5052-5079
		HC5051-5061	HF5054-5074
2017 Travel Star Fifth Wheels	H2	KJ5051-5053	KP5056-5062
		KK5054-5061	KR5052-5058
		KL5053-5058	
2017 Solstice Super Lite FW	H2	SA5050-5077	
		SB5050-5051	
		SC5050-5051	

Parts Kit 16-035S





8 tubes of Self leveling Sealant

Shop Supplies

Caulk gun
Plastic putty stick

Fig 1-4: Inspect items mounted on the roof for signs of sealant **cracking**.

Some of the areas you may find cracked sealant.



REPLACING CRACKED SEALANT

**NOTE: ROOF AND OLD SEALANT MUST BE DRY BEFORE APPLYING NEW SEALANT.
IF OLD SEALANT IS WET, OR THE ROOF IS WET, NEW SEALANT BEING APPLIED WILL NOT STICK.**



- 1 Fig 5: Remove the sealant, using the plastic putty stick, push the sealant toward the entire item.


DO NOT USE ANY SHARP OBJECTS!

Fig 6: Mounted item with Sealant removed .



- 2 Fig 7: Apply self leveling sealant around the item liberally over the remaining sealant and onto the roof.

Fig 8: Proper amount of Sealant applied around the item.



- 3 Fig 9: On larger items like this skylight, remove the sealant material up to the edge of the skylight as done in Fig 5.

Fig 10: Apply self leveling sealant on the perimeter of the item overlapping the sealant on the edge of item as done in Fig 7.



4 Fig 11: Finished skylight with new sealant applied.



Fig 12: Close voids or pinholes by ***gently*** swirling your finger in a small circular pattern, gradually lifting your finger



903 SOUTH MAIN STREET • P.O. BOX 460 • MIDDLEBURY, IN 46540 • TELEPHONE: (800) 945-4787 • WWW.STARCRAFTRV.COM

December 2016

Technical Service Bulletin Notification TSB #16-035

Name
Address
City st zip
Country

Dear Valued Starcraft Dealer:

Starcraft has determined that certain Model Year 2017 Solstice and Solstice Super Lite Fifth Wheels and Travel Star Fifth Wheels require inspection for cracks in the roof sealant applied around all attachments on the roof.

Our records indicate the following Fifth Wheel is part of your current inventory and requires the repair prior to being retail sold.

Serial number

If you have sold the vehicle listed, please contact the current owner regarding this Service Bulletin and process the Warranty Registration of your customer. All information concerning this TSB is available to you on Starcraft Connect under the Service and Parts Tab. If you have questions, please contact Starcraft Customer Service at 800-945-4787.

We apologize for any inconvenience this may cause. However, we are confident that this improvement will contribute to our Customers' continued satisfaction with their Starcraft fifth wheel.

Sincerely,
Starcraft



903 SOUTH MAIN STREET • P.O. BOX 460 • MIDDLEBURY, IN 46540 • TELEPHONE: (800) 945-4787 • WWW.STARCRAFTRV.COM

December 2016

Technical Service Bulletin Notification TSB #16-035

Unit Serial Number: «SERIAL_»

Name

Address

City st zip

Country

Dear Valued Starcraft Customer:

Starcraft has determined that certain Model Year 2017 Solstice and Solstice Super Lite Fifth Wheels and Travel Star Fifth Wheels require inspection for cracks in the roof sealant applied around all attachments to the roof.

Our records indicate that your fifth wheel is affected by this Service Bulletin. Please contact your nearest Starcraft dealer to schedule an appointment and present this letter as authorization to have the procedure completed. This procedure will be performed at no cost to you.

If you have sold or traded your vehicle, or for any reason cannot have this service performed, please contact the Starcraft Customer Service Department at 800-945-4787.

We apologize for any inconvenience this may cause. However, we are confident that this improvement will contribute to your continued satisfaction with your fifth wheel.

Sincerely,
Starcraft