



Tiffin Motorhomes, Inc.
105 2nd Street NW
Red Bay, AL 35582
256-356-8661

Service Bulletin 50 Cancellation

Replacement of Lower Sealing Holder on Kingpin Mounting on certain Allegro Bus and Phaeton Motorhomes built on PowerGlide Chassis equipped with ZF front axles, 2009-2016

December 15, 2016

Dear Tiffin Motorhome Customer,

In October of 2015 we notified 2010-2011 model year Allegro Buses owners of a Service Bulletin requiring replacement of the front suspension lower king pin seal caps. Our records indicate that you are one of the customers notified of this Service Bulletin.

Early field inspections/replacements of the lower king pin seal caps on many vehicles did not reveal the wear concern that initially prompted the release of Service Bulletin 50. An additional study, and measurement, of 20 units with varying mileage was performed by ZF engineers at Tiffin in January of 2016. No unusual wear was found during this study.

The January study revealed that the Service Bulletin requiring replacement of the king pin seal cap is not necessary for ZF suspensions used in recreational vehicles. This letter is to inform you that Service Bulletin 50 has now officially been canceled.

Thank you,

Tiffin Motorhomes, Inc.