

Date	Expiration	Release	Page
03 2016	03 2018	0	1(3)

Initial release

14 mars 2016

BATTERY DECAL REPLACEMENT

Prevost vehicles

DESCRIPTION

On the vehicles affected by this bulletin, replace the battery connection decal by a new version.

MODEL YEAR(S) AND VEHICLES INVOLVED

NOTICE TO SERVICE CENTERS	
Verify vehicle eligibility by checking warranty bulletin status with SAP or via ONLINE WARRANTY SYSTEM available on Service / Warranty tab of Prevost website.	
Model	VIN
X3-45 Commuter Model Year : 2014 - 2016	The following individual vehicles: 2PCG33495EC73 <u>5590</u> , 2PCG33498EC73 <u>5602</u> . And from 4RKG33497F973 <u>7001</u> up to 4RKG33497G973 <u>7209</u> incl.
This bulletin does not necessarily apply to all the above-mentioned vehicles, some vehicles may have been modified before delivery. The owners of the vehicles affected by this bulletin will be advised by a letter indicating the Vehicle Identification Number (VIN) of each vehicle concerned.	

MATERIAL NEEDED

Order kit SP16-304:

Part No.	Description	Qty
060144	DECAL,M4 EL BATTERY CONNECTION	2

NOTE
Material can be obtained through regular channels.

Date	Expiration	Release	Page
03 2016	03 2018	0	2(3)

PROCEDURE



DANGER

Park vehicle safely, apply parking brake, stop engine. Prior to working on the vehicle, set the ignition switch to the OFF position and trip the main circuit breakers equipped with a trip button. On Commuter type vehicles, set the battery master switch (master cut-out) to the OFF position.

- 1) Open the engine compartment curb-side door (Fig. 1, Item 2,)




Figure 1

- 2) Locate instruction decal on the battery cover. (Fig. 2, 3)




Figure 2: Battery cover instruction decal




Figure 3: Decal location

- 3) Remove and store the covers following instructions on the decal.

- 4) On the battery access door, remove existing decal #069416.
- 5) Clean the surface and affix new decal #060144.




Figure 4

- 6) Open the battery access door.
- 7) On the inside of the access door, remove existing decal #069416.
- 8) Clean the surface and affix new decal #060144.
- 9) Close battery access door.
- 10) Place covers back in place
- 11) Close the engine compartment curb-side door.




Figure 5

PARTS / WASTE DISPOSAL

Discard waste according to applicable environmental regulations (Municipal/State[Prov.]/ Federal)

ESTIMATED TIME

The time required to perform this special bulletin is approximately 30 minutes.

OTHER

VBC Bulletin	N/A
Fail Code	06.11
Defect Code	09
System Condition	B
Causal Part	069416

Prevost engages in a continuous program of testing and evaluating to provide the best possible product. Prevost, however, is not committed to, or liable for updating existing products.