



Tech Tips

TT 90-16-01

Date: October 7, 2016

2000-2001 Beetle – Cruise Control/Speedometer Inoperative after Instrument Cluster Replacement – P0501

After a new instrument cluster has been installed, the cruise control or speedometer may be inoperative. Fault P0501 may be present as well. To address, perform the following circuit modifications at pins 3 and 28, of the blue T32 instrument panel connector:

Cut both wires and splice them together using one butt end connector and the tools from the VAS 1978 wiring kit. Splice both wires together from the instrument cluster side, and both wires from the vehicle harness side into the butt connector.