


PROFI Dealer Vehicle Information Request Form

MY(s) Affected:	2009-2016	Issue ID #	2016-018
Vehicle Model(s):	Tiguan	Photos (if applicable): 	
VIN Range (if applicable):	All		
Engine Code(s):	CCTA		
Gearbox (Manual / Automatic):	All		
Issue Description / Symptom: Vehicle requires turbo replacement			
Workshop Problem Validation Procedure: Remove Turbocharger			
Required Actions: Obtain a photo of the wastegate rod and lever area as shown. Email photos to Michael Storms.			
		VWoA Contact Information:	
		Requestor:	Michael Storms
		E-mail:	michael.storms@vw.com
		Phone Number:	248-754-6042
		Alternative Contact:	
		E-mail:	
		Phone Number:	