

# Technical Service Bulletin

#### 96 Hazard lights flashing for no reason - A4/Q7

96 16 11 2045767/1 October 28, 2016.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A4	2017	All	Not applicable
Q7	2017	All	Not applicable

## Condition

#### **Customer states:**

• The anti-theft alarm goes off for no obvious reason, mainly in strong rain. The hazard lights will blink rapidly. However, the alarm horn may not sound.

#### Workshop findings:

- No event entries are logged.
- In the measured value blocks for the comfort system central control module, J393 (address word 46) you may find "Backup\_horn\_alarm\_trigger\_cycle\_data no communication" as the source for the alarm.

### **Technical Background**

When a key is not in range of the vehicle during very heavy rain, flowing water or other objects could interfere with the hands-free tailgate release sensor and trigger the anti-theft alarm system in the comfort system control module J393 (address word 46).

### **Production Solution**

Not applicable.

### **Service**

Postpone repairs; a parts replacement does not fix the problem. When a solution is available it will be published as a revision to this bulletin.

<sup>© 2016</sup> Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



# **Technical Service Bulletin**

### Warranty

This TSB is informational only and not applicable to any Audi Warranty.

## **Additional Information**

All parts and service references provided in this TSB (2045767) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.

The following Technical Service Bulletin(s) will be necessary to complete this procedure:

• TSB 2045051, 57 Anti-theft alarm goes off without cause.

©2016 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.

© 2016 Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.