

8/24/2016 MY15, 16 BU MY16 FB

## GPOP - Issue Review System

**Part Number:** 68321236A\$, 68321233A\$

**Part Description:** RF Hub Module

---

**Issue Description:** DTC, U1765-87 "RFHM (Radio Frequency Hub Module) - Missing Message" may appear in a stored state on a ignition power cycle. No troubleshooting or parts replacement is necessary if this code is stored as the system is functioning to design.~

~

—~

Contact us at [CAGRIS@Chrysler.com](mailto:CAGRIS@Chrysler.com) for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.

---