CONDITION

In some 2016 MY Tacoma vehicles, customers may experience a vibration feeling when braking or on deceleration. This can occur at various speeds or pedal application forces.

RECOMMENDATIONS

- Please do not disassemble. Create a TAS case and contact Technical Assistance (TAS) to submit details on any vehicle identified matching the condition described in this document prior to repair.
- If you are attempting to contact TAS on a weekend or TMS holiday, continue with diagnosis and submit the requested information on the next available work day. Retain all replaced parts and technician notes for possible review with TMS TAS Product Engineer.

LINK REFERENCES

This Tech Tip does not contain any link references