



# Service Bulletin

File in Section: -

Bulletin No.: 16-NA-226

Date: October, 2016

## INFORMATION

**Subject:** Information on Incorrect Tire Valve Stems Being Installed

| Brand:    | Model:  | Model Year: |      | VIN: |    | Engine: | Transmission: |
|-----------|---------|-------------|------|------|----|---------|---------------|
|           |         | from        | to   | from | to |         |               |
| Chevrolet | Express | 2015        | 2017 |      |    |         |               |
| GMC       | Savana  |             |      |      |    |         |               |

|                                   |                                       |
|-----------------------------------|---------------------------------------|
| <b>Involved Region or Country</b> | North America and N.A. Export Regions |
| <b>Additional Options (RPO)</b>   | Valve RPOs (8R2, 8R3)                 |

The purpose of this bulletin is to inform technicians and dealership personnel that when replacing the rubber tire valve stems, **DO NOT** replace the original stems with the brass valve stems **UNLESS** the vehicle comes equipped with the RPOs listed above.

The increased length of the brass valve stems may cause an interference on standard vehicle applications.

|                 |   |
|-----------------|---|
| <b>Version</b>  | 2   |
| <b>Modified</b> | Oct. 18, 2016 – Adding the 2017 Model Year. |

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, **DO NOT** assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



**WE SUPPORT VOLUNTARY  
TECHNICIAN  
CERTIFICATION**