

June 1, 2016 MY 16 L A

GPOP - Issue Review System

Part Number: 5LE49LA8A\$, 5LE49YSAA\$

Part Description: Console Lid

Issue Description: LA ONLY: If you are replacing the console lid because the latch is broken, please also replace the console base in addition to the console lid. Please call Mike Wicker on cell (248) 821-9350 prior to replacing the components. If you don't receive a response within 15 minutes, please continue with normal repair procedure.

~

—~

Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
