

3/10/16

MY15, 16

MK

GPOP - Issue Review System

Part Number: L0003157

Part Description: Tail Lamp Bulb

Issue Description: If the tail lamp bulb (L00003157) on a 2015 or 2016 MK is being replaced for any reason, engineering would like to have the bulb and the entire lamp assembly replaced and returned for analysis. If you have any questions, please contact Brigitte Wicks at cell (248) 202-9869. Also please make sure to send the part to Brigitte's attention when it is returned. Thank you.

~
Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquiries. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
