

2/26/16

MY16 LA

GPOP - Issue Review System

Part Number: 5LE49LV5A\$, 5LE51LV5A\$

Part Description: Floor Center Console Panel & Lid

Issue Description: This TechTip applies to 2016MY Challenger Scat Pack (LADX22) ONLY. Silver color stitching on floor center console panel and lid is no longer available for replacement. Replacement parts will have color stitching that matches vehicle's interior trim stitching, ex. seats (Sepia, Red, or Tungsten). If a repair requires the panel or lid to be replaced, then the floor console panel and lid are to be replaced together for color conformity.

~
Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquires. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.