

2/26/16

MY15 KL

GPOP - Issue Review System

Part Number: 68194941A\$

Part Description: Seal, Sunroof Front Glass

Issue Prior to ordering this part to correct a BSR issue, apply Mopar Part 04773427 to
Description: contact surface of existing sunroof seal. This may fix the issue.~

~
Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP
Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or
part order inquires. Please include the Part Number (s) and Tech Tip Part
Description of the Tech Tip you are referencing for our tracking system.