

5/11/2016 MY 15 VM

## **GPOP - Issue Review System**

**Part Number:** BB048750A\$

**Part Description:** Battery

---

**Issue Description:** Prior to replacing the battery, please check the component to determine if there is any acid leaking from the unit. If the answer is yes, please contact Bruce Davis at Cell (248) 613-5637 for further instructions. If the answer is no, please proceed with the battery replacement.~

~ ~

Contact Us at [CAGRIS@Chrysler.com](mailto:CAGRIS@Chrysler.com) for feedback related only to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquiries. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.

---