

2/26/16

MY15 KL

GPOP - Issue Review System

Part Number: 68194943A\$

Part Description: Frame, Sunroof Dual Pane

Issue Description: Prior to ordering this part to correct a BSR issue, apply Mopar Part 04773427 to contact surface of the sunroof seal. This may fix the issue.~

~
Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquires. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.